

Fred Meyer Subdivision


A Resubdivision and Renumbering of

A Portion of Lots 13, 14 and 15
and of the Vacated Streets
Adjoining said Lots
In "Peters Subdivision"
Being a Part of
NE 1/4 NE 1/4, Section 9,
Township 10 South,
Range 17 East,
Boise Meridian,
Twin Falls County, Idaho
2000

Twin Falls County, Idaho
Recorded for:
EHM ENGINEERS
01:14pm Apr. 13, 2000
2000-005497
No. of Pages: 3 Fee: \$33.00
ROBERT S. FORT
Ex-Officio Recorder
Deputy: CD

North

0 50' 100' 200'
SCALE IN FEET



Health Certificate

Sanitary restrictions as required by Idaho Code Title 50, Chapter 13, have been satisfied. Sanitary restrictions may be reimposed, in accordance with Idaho Code Title 50, Chapter 13, Section 50-1326, by the issuance of a certificate of disapproval.


Date: Mar 23, 2000
South Central District Health Dept., EHS

Curve Data

CURVE	DELTA	RADIUS	ARC	CHORD	TANGENT	CHORD BRG
1	16°15'31"	250.00	70.94	70.70	35.71	S 83°41'08"W
2	16°15'31"	250.00	70.94	70.70	35.71	N 83°41'08"E
3	16°15'31"	250.00	70.94	70.70	35.71	S 80°03'21"E
4	16°15'27"	250.00	70.94	70.70	35.71	N 80°03'37"W
5	10°45'23"	250.00	46.93	46.87	23.54	N 77°18'17"W

Legend

Subdivision Boundary Line	—
Lot Line	—
Easement Line	- - -
Found Brass Cap	⊗
Found 1/2" Rebar & Cap	○
Found 5/8" Rebar	○
Found Aluminum Cap (LS 6018)	●
Set 5/8" Rebar & Cap (LS 1000)	⊙
Set 1/2" x 24" Rebar & Cap (LS 1000)	•



EHM Engineers, Inc.
ENGINEERS/SURVEYORS/PLANNERS